

PROCESS TO CALIBRATE THE GRINDER

A


Necessary equipment



1 → Gauge Block KO-CY1014

B

Defective part



C

Process of calibration

1



2



3




In 3 sec. MAX

4




5



6

Restart the process










EA9000../70.




30/01/2013

BARISTA

1/2



Process in progress ...



EA9000../70.

30/01/2013

BARISTA

2/2